

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
ASYmw-001	04/24/19	The guard posts are heavily rusted. The well paint and ID are in good condition.	The guard posts, well casing, and well ID were painted in August 2019.
ASYmw-002	04/24/19	The guard posts have minor rust. The well paint and ID are in good condition.	The guard posts, well casing, and well ID were painted in August 2019.
ASYmw-003	04/24/19	The guard posts are heavily rusted. The well paint is in good condition, but the ID is fading.	The guard posts, well casing, and well ID were painted in August 2019.
ASYmw-004	04/24/19	The guard posts are heavily rusted. The well paint is in good condition, but the ID is fading.	The guard posts, well casing, and well id were painted in August 2019.
ASYmw-005	04/24/19	The guard posts are heavily rusted. The well paint is in good condition, but the ID is not visible. The well pad is loose from freeze/thaw.	The guard posts, well casing, and well ID were painted in August 2019.
ASYmw-006	04/24/19	The guard posts are heavily rusted. The well paint is in good condition, but the ID is starting to fade.	The guard posts, well casing, and well ID were painted in August 2019.
ASYmw-007	04/24/19	The guard posts are heavily rusted. The well paint and ID are in good condition.	The guard posts, well casing, and well ID were painted in August 2019.
ASYmw-008	04/24/19	The guard posts are heavily rusted. The well paint is in good condition, but the ID is faded and barely visible.	The guard posts, well casing, and well ID were painted in August 2019.
ASYmw-009	04/24/19	The guard posts are heavily rusted. The well paint is in good condition, but the ID is faded and hard to read.	The guard posts, well casing, and well ID were painted in August 2019.
ASYmw-010	04/24/19	The guard posts are heavily rusted. The well paint is in good condition, but the ID is starting to fade.	The guard posts, well casing, and well ID were painted in August 2019.
B12mw-010	04/25/19	The guard posts are heavily rusted and leaning. The well paint is in good condition, but the ID is faded and hard to read.	None.
B12mw-011	04/25/19	The guard posts are heavily rusted. The well paint is in good condition, but the ID is very slightly faded.	None.
B12mw-012	04/25/19	The guard posts have moderate rust. The well paint is in good condition, but the full ID is not visible. The AOC ID looks to have been repainted, but the well number has not been repainted.	None.
B12mw-013	04/25/19	The well is in good condition; no issues.	None.
BKGmw-004	04/29/19	The guard posts and well paint show minor rust. The ID is not visible.	None.
BKGmw-005	04/24/19	The guard posts and well paint show minor rust. The ID is very slightly faded.	The guard posts, well casing, and well ID were painted in August 2019.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
BKGmw-006	04/24/19	The guard posts and well paint show minor rust. The ID is in good condition.	None.
BKGmw-008	04/25/19	The guard posts and well paint show minor rust. The ID is beginning to fade.	The guard posts, well casing, and ID were painted in November 2019.
BKGmw-010	04/25/19	The guard posts and well paint show moderate rust. The ID is faded. The hinge on the well lid is broken and cannot be secured.	The well lid hinge was repaired in December 2019. The guard posts, well casing, and well ID were painted in December 2019. The bollards were straightened in December 2019.
BKGmw-012	04/29/19	The guard posts and well paint show very minor rusting. The ID is in good condition.	The guard posts, well casing, and ID were painted in May 2019.
BKGmw-013	04/24/19	The guard posts and well paint show very minor rusting. The ID is in good condition. The hinge on the well lid is broken and cannot be secured. The compression cap was installed on 4/25/19.	The guard posts, well casing, and well ID were painted in December 2019. The well lid hinge was repaired in December 2019.
BKGmw-015	04/24/19	The guard posts and well paint show moderate rust. The ID is faded.	None.
BKGmw-016	04/24/19	The guard posts and well paint show minor rusting. The ID is beginning to fade. The hinge on the well lid is broken and cannot be secured.	The guard posts, well casing, and well ID were painted in December 2019. The well lid hinge was repaired in December 2019.
BKGmw-017	04/24/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
BKGmw-018	04/24/19	The guard posts and well paint show minor rusting. The ID is in good condition.	None.
BKGmw-019	04/24/19	The guard posts and well paint show very minor rusting. The ID is in good condition. The hinge on the well lid is broken and cannot be secured.	The well lid hinge was repaired in December 2019.
BKGmw-020	04/23/19	The guard posts and well paint show very minor rusting. The ID is in good condition.	The guard posts, well casing, and well ID were painted in August and September 2019.
BKGmw-021	04/29/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
BKGmw-022	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
BKGmw-023	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
BKGmw-024	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
BKGmw-025	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
CBLmw-001	04/24/19	The guard posts show moderate to heavy rusting. The well paint and ID are in good condition.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
CBLmw-002	04/24/19	The guard posts show heavy rusting. The well paint and ID are in good condition.	None.
CBLmw-003	04/24/19	The guard posts show heavy rusting. The well paint and ID are in good condition.	None.
CBLmw-004	04/24/19	The guard posts show moderate rusting. The well paint and ID are in good condition.	None.
CBLmw-005	04/24/19	The well is in good condition; no issues.	None.
CBPmw-001	04/23/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
CBPmw-002	04/23/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
CBPmw-003	04/23/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
CBPmw-004	04/23/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
CBPmw-005	04/23/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
CBPmw-006	04/23/19	The guard posts and well paint show minor rusting. The ID is showing minor fading.	None.
CBPmw-007	04/23/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
CBPmw-008	04/23/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
CBPmw-009	04/23/19	The well is in good condition. The paint is white (incorrect color).	None.
CPmw-001	04/25/19	The well is in good condition; no issues.	None.
CPmw-002	04/29/19	The guard posts show minor rusting. The ID is in good condition.	None.
CPmw-003	04/25/19	The guard posts show moderate rusting. The ID is in fair condition. Flush mount well; the bolt holders are stripped and the lid cannot be secured.	The flush mount bolts were repaired in November 2019.
CPmw-004	04/25/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	The guard posts, well casing, and well ID were painted in July 2019.
CPmw-005	04/25/19	The guard posts and well paint show minor rusting. The ID is faded and not visible.	The guard posts, well casing, and well ID were painted in July 2019.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
CPmw-006	04/25/19	The guard posts and well paint show moderate rusting. The ID is faded and not visible.	None.
DA1tw-001	04/24/19	N/A – The temporary well was installed in October 2018.	None.
DA2mw-104	04/23/19	The guard posts and well paint show minor rust. The ID is faded.	None.
DA2mw-105	04/23/19	The guard posts and well paint show minor rusting. The ID is in good condition.	None.
DA2mw-106	04/23/19	The guard posts and well paint show minor rusting. The ID is in good condition.	None.
DA2mw-107	04/23/19	The guard posts and well paint show minor rusting. The ID is in good condition.	None.
DA2mw-108	04/23/19	The guard posts and well paint show minor rusting. The ID is hard to read due to paint chipping.	None.
DA2mw-109	04/23/19	The guard posts and well paint show minor rust. The ID is in good condition. The well pad is elevated off of the ground due to frost heave.	None.
DA2mw-110	04/23/19	The paint and ID are in good condition. The well pad is raised off of the ground due to frost heave.	None.
DA2mw-111	04/23/19	The guard posts and well paint show minor rusting. The ID is hard to read due to paint chipping. The well pad is elevated due to frost heave.	None.
DA2mw-112	04/23/19	The guard post and well paint are in good condition. There is slight paint chipping around the ID.	None.
DA2mw-113	04/23/19	The guard post and well paint are in good condition. There is paint chipping around the ID.	None.
DA2mw-114	04/23/19	The well is in good condition. The paint is white (incorrect color).	None.
DA2mw-115	04/23/19	The well is in good condition. The paint is white (incorrect color).	None.
DET-001B	04/23/19	The guard posts and well paint show minor rusting. The ID is in good condition. The well pad is elevated due to frost heave.	None.
DET-002	04/23/19	The guard posts and well paint show moderate rusting. The ID is in good condition. One guard post is leaning.	None.
DET-003	04/23/19	The guard posts and well paint show moderate rusting. The ID is faded and not visible.	None.
DET-004	04/23/19	The guard posts and well paint show moderate rusting. The ID is in good condition.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
EBGmw-123	04/25/19	The guard posts and well paint show minor rusting. The ID is beginning to fade.	None.
EBGmw-124	04/25/19	The well is in good condition; no issues.	None.
EBGmw-125	04/25/19	The well is in good condition; the ID is beginning to fade.	None.
EBGmw-126	04/25/19	The guard posts and well paint show very minor rusting. The ID is faded and hard to read. Some posts are leaning.	None.
EBGmw-127	04/25/19	The well is in good condition; no issues.	None.
EBGmw-128	04/25/19	The ID is slightly faded; no other issues.	None.
EBGmw-129	04/25/19	The guard posts show minor rusting. The ID is in good condition.	None.
EBGmw-130	04/25/19	The well is in good condition; the ID is beginning to fade.	None.
EBGmw-131	04/25/19	The paint is in good condition; there is a crack in the well pad.	None.
FBQmw-166	04/24/19	The guard posts and well paint are in good condition. The ID is faded and not visible.	The guard posts, well casing, and well ID were painted in August 2019.
FBQmw-167	04/24/19	The guard posts and well paint are in good condition. The ID is faded and not visible.	The guard posts, well casing, and well ID were painted in August 2019.
FBQmw-168	04/24/19	The well is in good condition; no issues.	The well ID was repainted in August 2019.
FBQmw-169	04/24/19	The paint is in good condition. The well pad is elevated due to frost heave.	The cracks in the well pad were repaired and the bollard was straightened in December 2019.
FBQmw-170	04/24/19	The guard posts and well paint are in good condition. The ID is faded and not visible.	The guard posts, well casing, and well ID were painted in August 2019.
FBQmw-171	04/24/19	The guard posts and well paint are in good condition. The ID is faded.	The well ID was repainted in August 2019.
FBQmw-172	04/24/19	The guard posts and well paint are in good condition. The ID is faded and not visible.	None.
FBQmw-173	04/24/19	The guard posts and well paint are in good condition. The ID is faded.	None.
FBQmw-174	04/24/19	The guard posts and well paint are in good condition. The ID is faded.	None.
FBQmw-175	04/24/19	The paint is in good condition. The well cap does not sit flush with the top of the PVC (can't be pushed down).	None.
FBQmw-176	04/24/19	The well is in good condition; no issues.	The guard posts, well casing, and well ID were painted in August 2019.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
FBQmw-177	04/24/19	The guard posts and well paint are in good condition. The ID is faded and not visible.	The guard posts, well casing, and well ID were painted in August 2019.
FWGmw-001	04/29/19	The well is in good condition. The paint is white (incorrect color).	The guard posts, well casing, and well ID were painted in October 2019.
FWGmw-002	04/29/19	The well is in good condition. The paint is white (incorrect color).	None.
FWGmw-003	04/24/19	The guard posts and well paint show moderate rusting. The ID is in good condition.	None.
FWGmw-004	04/29/19	The guard post paint is in good condition. Minor chipping on the well paint around the ID has occurred.	None.
FWGmw-005	04/24/19	The well is in good condition; no issues.	None.
FWGmw-006	04/24/19	The guard posts and well paint show minor rusting/chipping. Chipping near the ID makes it hard to read.	None.
FWGmw-007	04/24/19	The guard post paint is in in good condition. Chipping near the well ID makes it hard to read. The well pad has a hairline crack.	None.
FWGmw-008	04/24/19	The guard posts and well paint show minor chipping/rusting. The ID is in good condition, but may be affected by surrounding chipping.	None.
FWGmw-009	04/24/19	The guard posts show minor rusting, and moderate rusting/chipping on the well paint has occurred. The ID is visible but affected by surrounding paint chipping.	None.
FWGmw-010	04/25/19	The guard posts are in good condition. The well paint is heavily rusted/chipped. The ID is not visible.	None.
FWGmw-011	04/25/19	The guard posts and well show minor rust/chipping. The paint is white (incorrect color).	None.
FWGmw-012	04/25/19	The well is in good condition. The paint is white (incorrect color).	None.
FWGmw-013	04/23/19	The paint is in good condition; the well pad is cracked.	None.
FWGmw-014	04/24/19	The well is in good condition. The paint is white (incorrect color).	The guard posts, well casing, and well ID were painted in August 2019.
FWGmw-015	04/29/19	The well is in good condition; minor rust/chipping on the well has occurred.	None.
FWGmw-016	04/29/19	The well is in good condition; minor fading on the ID has occurred.	None.
FWGmw-018	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
FWGmw-019	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
FWGmw-020	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
FWGmw-021	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
FWGmw-022	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
FWGmw-023	04/23/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
FWGmw-024	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was added in October 2019.
LL1mw-063	04/25/19	The guard posts show moderate rusting; the well paint is in good condition. The ID is faded and hard to read.	None.
LL1mw-064	04/25/19	The guard posts show moderate rusting. The well paint and ID are in good condition.	None.
LL1mw-065	04/25/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is faded.	None.
LL1mw-067	04/25/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is faded.	None.
LL1mw-078	04/25/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL1mw-079	04/25/19	The guard posts and well paint show minor rusting. The ID is in good condition.	None.
LL1mw-080	04/25/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL1mw-081	04/25/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL1mw-082	04/25/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL1mw-083	04/25/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL1mw-084	04/25/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL1mw-085	04/25/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL1mw-086	04/25/19	The well is in good condition; no issues.	None.
LL1mw-087	04/25/19	The guard posts are in good condition. Rust/chipping on the well paint makes the ID hard to read.	None.
LL1mw-088	04/25/19	The guard posts are in good condition. The well is not painted and no ID is present.	None.
LL1mw-089	04/25/19	The well is in good condition, but the ID needs to be painted on.	The well ID was added in October 2019.
LL2mw-059	04/25/19	The guard posts show minor to moderate rusting. The well paint and ID are in good condition.	None.
LL2mw-060	04/25/19	The well is in good condition; no issues.	The guard posts, well casing, and well ID were painted in July 2019.
LL2mw-261	04/29/19	The guard posts and well paint show minor rusting. The ID is slightly faded.	None.
LL2mw-262	04/29/19	The guard posts and well paint show minor rusting. The ID is slightly faded.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
LL2mw-263	04/29/19	The guard posts and well paint show minor rusting. The ID is slightly faded.	None.
LL2mw-264	04/29/19	The guard posts show minor rusting. The well paint is moderately to heavily rusting/chipping, and the ID is not visible.	None.
LL2mw-265	04/29/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL2mw-266	04/29/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL2mw-267	04/29/19	The guard posts and well paint show minor rusting. The ID is faded. One guard post is leaning.	None.
LL2mw-268	04/29/19	The guard posts and well paint show minor rusting. The ID is slightly faded.	None.
LL2mw-269	04/29/19	The guard posts and well paint show minor rusting. The ID is slightly faded.	None.
LL2mw-270	04/29/19	The guard posts and well paint show minor rusting. The ID is faded and not visible.	None.
LL2mw-271	04/29/19	The guard posts are in good condition. The well casing is not painted and there is no ID.	The guard posts, well casing, and well ID were painted in July 2019.
LL2mw-272	04/29/19	The well is in good condition, but the ID needs to be painted on.	The well ID was added in October 2019.
LL3mw-232	04/25/19	The guard posts and well paint show minor rusting. The ID is slightly faded.	None.
LL3mw-233	04/25/19	The guard posts and well paint show minor rusting. The ID is slightly faded.	None.
LL3mw-234	04/25/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read. The well lid is cracked but can be closed and secured.	None.
LL3mw-235	04/25/19	The guard posts and well paint show minor rusting. The ID is starting to fade.	None.
LL3mw-236	04/25/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
LL3mw-237	04/25/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read. One post is leaning over.	None.
LL3mw-238	04/25/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
LL3mw-239	04/25/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL3mw-240	04/25/19	The well is in good condition; no issues.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
LL3mw-241	04/25/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.
LL3mw-242	04/25/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	The guard posts, well casing, and well ID were painted in May 2019.
LL3mw-243	04/25/19	The well is in good condition; no issues.	The guard posts, well casing, and well ID were painted in May 2019.
LL3mw-244	04/25/19	The well is in good condition; white paint (incorrect color).	The guard posts, well casing, and well ID were painted in May 2019.
LL3mw-245	04/25/19	The well is in good condition; no issues.	The guard posts, well casing, and well ID were painted in May 2019.
LL3mw-246	04/24/19	The guard posts show minor rusting. The well casing is not painted, and there is no ID.	None.
LL4mw-193	04/25/19	The guard posts and well show minor rusting. The ID is beginning to fade.	The guard posts, well casing, and well ID were painted in July 2019.
LL4mw-194	04/25/19	The guard posts and well show minor rusting. The ID is beginning to fade.	The guard posts, well casing, and well ID were painted in May 2019.
LL4mw-195	04/25/19	The well was repainted during the April 2019 event; good condition.	The guard posts, well casing, and well ID were painted in July 2019.
LL4mw-196	04/25/19	The guard posts and well show minor rusting. The ID is beginning to fade.	The guard posts, well casing, and well ID were painted in May 2019.
LL4mw-197	04/25/19	The guard posts and well show minor rusting. The ID is beginning to fade.	The guard posts, well casing, and well ID were painted in May 2019.
LL4mw-198	04/25/19	The guard posts and well show moderate rusting. The ID is beginning to fade.	The guard posts, well casing, and well ID were painted in July 2019.
LL4mw-199	04/25/19	The guard posts and well show minor rusting. The ID is beginning to fade.	The guard posts, well casing, and well ID were painted in July 2019.
LL4mw-200	04/25/19	The well was repainted during the April 2019 event; the well is in good condition.	The guard posts, well casing, and well ID were painted in May 2019.
LL4mw-201	04/25/19	The guard posts and well show minor rusting. The ID is beginning to fade.	The guard posts, well casing, and well ID were painted in July 2019.
LL5mw-001	04/24/19	The guard posts show heavy rusting. The well paint is in good condition, but the ID is faded.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
LL5mw-002	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is faded.	None.
LL5mw-003	04/24/19	The guard posts show heavy rusting. The well paint is in good condition, but the ID is faded.	None.
LL5mw-004	04/24/19	The guard posts show heavy rusting. The well paint is in good condition, but the ID is faded.	None.
LL5mw-005	04/24/19	The guard posts show heavy rusting. The well paint is in good condition, but the ID is faded.	None.
LL5mw-006	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is faded.	None.
LL6mw-001	04/24/19	The guard posts show heavy rusting, but the ID is still visible on one post. Flush mount well; one bolt holder is missing, but the well can still be secured.	The flush mount bolts were repaired in November 2019.
LL6mw-002	04/24/19	The guard posts and well show heavy rusting. The ID has been rusted over and is not visible.	None.
LL6mw-003	04/24/19	The guard posts and well show moderate rusting. The ID has been rusted over.	None.
LL6mw-004	04/24/19	The guard posts and well show moderate rusting. The ID is in good condition.	None.
LL6mw-005	04/24/19	The guard posts and well show moderate rusting. The ID has been rusted over.	None.
LL6mw-006	04/24/19	The guard posts show heavy rusting, but the ID is still visible on one post. Flush mount well.	None.
LL6mw-007	04/24/19	The guard posts show heavy rusting, but the ID is still visible on one post. Flush mount well; one bolt holder is stripped and the other is missing. The well cannot be secured.	The flush mount bolts were repaired in November 2019.
LL6mw-008	04/24/19	The well is in good condition; no issues.	None.
LL6mw-009	04/24/19	The well is in good condition; no issues.	None.
LL7mw-001	04/23/19	The guard posts show heavy to moderate rusting, but the well paint is in good condition. The ID is faded and not visible.	None.
LL7mw-002	04/23/19	The guard posts show heavy rusting, but the well paint is in good condition. The ID is faded and not visible.	None.
LL7mw-003	04/23/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is faded and not visible.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
LL7mw-004	04/23/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is faded and not visible.	None.
LL7mw-005	04/23/19	The guard posts show heavy to moderate rusting, but the well paint is in good condition. The ID is faded and hard to read.	None.
LL7mw-006	04/23/19	The guard posts show heavy to moderate rusting, but the well paint is in good condition. The ID is faded and hard to read.	None.
LL8mw-001	04/23/19	The guard posts show heavy to moderate rusting, but the well paint is in good condition. The ID is in good condition.	None.
LL8mw-002	04/24/19	The guard posts show heavy to moderate rusting, but the well paint is in good condition. The ID is faded and not visible.	None.
LL8mw-003	04/24/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is starting to fade. The well pad is cracked. The well casing has two dent marks.	The concrete base cracks were filled in December 2019.
LL8mw-004	04/24/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is starting to fade.	None.
LL8mw-005	04/24/19	The guard posts show heavy rusting, but the well paint is in good condition. The ID is faded and not visible. One post is leaning over. The well pad is cracked.	The concrete base cracks were filled in December 2019. The bollard was straightened in December 2019.
LL8mw-006	04/24/19	The guard posts show moderate rusting, but the well paint is in good condition. Half of the ID is faded and not visible. The well pad is cracked.	The concrete base cracks were filled in December 2019.
LL9mw-001	04/24/19	The guard posts and well paint show moderate rusting. The ID is visible on one post but rusted over on the casing. One post is leaning over.	The guard posts, well casing, and well ID were painted in May 2019.
LL9mw-002	04/24/19	The guard posts show minor to moderate rusting. The ID is rusted over. One post is leaning over.	None.
LL9mw-003	04/24/19	The guard posts and well paint show minor rusting. The ID is faded and not visible.	None.
LL9mw-004	04/24/19	The guard posts and well paint show moderate rusting. The ID is rusted over.	None.
LL9mw-005	04/24/19	The guard posts and well paint show moderate rusting. The ID is rusted over.	None.
LL9mw-006	04/24/19	The guard posts and well paint show moderate rusting. The ID is rusted over.	None.
LL9mw-007	04/24/19	The guard posts show minor rusting. The ID on the post is faded and	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
		not visible. Flush mount well.	
LL10mw-001	04/24/19	The guard posts show severe rusting, but the well paint is in good condition. The ID is faded and not visible.	None.
LL10mw-002	04/24/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is faded and not visible.	None.
LL10mw-003	04/24/19	The guard posts show severe rusting, but the well paint is in good condition. The ID is faded and not visible.	None.
LL10mw-004	04/24/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is faded and not visible.	None.
LL10mw-005	04/24/19	The guard posts show severe rusting, but the well paint is in good condition. The ID is faded and not visible.	None.
LL10mw-006	04/24/19	The guard posts show severe rusting, but the well paint and ID are in good condition. The well pad is cracked.	None.
LL11mw-001	04/23/19	The guard posts and well paint show minor rusting. The ID is faded.	None.
LL11mw-002	04/23/19	The guard posts show moderate rusting. The ID is faded and not visible. Flush mount well; both bolt holders are stripped and the lid cannot be secured.	The flush mount bolts were repaired in November 2019.
LL11mw-003	04/23/19	The guard posts show minor rusting. The ID is faded and not visible.	None.
LL11mw-004	04/23/19	The guard posts show minor to moderate rusting, but the ID is in good condition. Flush mount well; the bolt holders are broken off and the lid cannot be secured.	The flush mount bolts were repaired in November 2019.
LL11mw-005	04/23/19	The guard posts show moderate rusting, but the ID is in okay condition. Flush mount well; one of the bolts is too small, but the lid can be secured.	The flush mount bolts were repaired in November 2019.
LL11mw-006	04/23/19	The guard posts show minor to moderate rusting, and the ID is faded and hard to read.	None.
LL11mw-007	04/23/19	The guard posts and well paint show minor rusting/chipping. The ID is in good condition. The well pad is cracked.	None.
LL11mw-008	04/23/19	The guard posts show minor to moderate rusting, and the ID is faded and hard to read. Flush mount well; both bolt holders are stripped and the lid cannot be secured.	The flush mount bolts were repaired in November 2019.
LL11mw-009	04/23/19	The guard posts show moderate rusting, and the ID is painted on the post and is fading. The well casing is not painted.	None.
LL11mw-010	04/23/19	The guard posts and well paint show minor rusting. The ID is faded and hard to read.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
LL11mw-011	04/23/19	The well is in good condition; no issues.	None.
LL11mw-012	04/23/19	All paint is in good condition. The well pad is cracked.	None.
LL12mw-088	04/25/19	The guard posts and well paint show minor rusting. The ID is in good condition.	The guard posts, well casing, and well ID were painted in August 2019.
LL12mw-107	04/25/19	The guard posts and well paint show minor rusting. The ID is fading.	None.
LL12mw-113	04/25/19	The guard posts and well paint are in good condition. The ID is fading.	The well ID was repainted in October 2019.
LL12mw-128	04/25/19	The guard posts show minor rusting. The well paint and ID are in good condition.	None.
LL12mw-153	04/25/19	The guard posts show minor rusting. The well paint and ID are in good condition.	The guard posts, well casing, and well ID were painted in December 2019.
LL12mw-154	04/25/19	The guard posts show minor rusting. The well paint and ID are in good condition.	The guard posts, well casing, and well ID were painted in December 2019.
LL12mw-182	04/25/19	The well appears to have been recently repainted and is in good condition.	The guard posts, well casing, and well ID were painted in July 2019.
LL12mw-182ss	04/25/19	The well appears to have been recently repainted and is in good condition.	The guard posts, well casing, and well ID were painted in July 2019.
LL12mw-183	04/25/19	The guard posts show minor rusting. The well paint and ID are in good condition.	The guard posts, well casing, and well ID were painted in September and October 2019.
LL12mw-184	04/25/19	The well is in good condition; no issues.	
LL12mw-185	04/25/19	The guard posts show minor rusting. The well paint and ID are in good condition.	The guard posts, well casing, and well ID were painted in October 2019.
LL12mw-186	04/25/19	The guard posts and well paint show minor rusting. The ID is in good condition.	The guard posts, well casing, and well ID were painted in December 2019.
LL12mw-187	04/25/19	The guard posts and well paint show minor rusting. The ID is in good condition.	The guard posts, well casing, and well ID were painted in October 2019.
LL12mw-188	04/25/19	The guard posts and well paint show minor rusting. The ID is in good condition.	The guard posts, well casing, and well ID were painted in October 2019.
LL12mw-189	04/25/19	The guard posts and well paint show minor rusting. The ID is in good condition.	The guard posts, well casing, and well ID were painted in December 2019.
LL12mw-242	04/25/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is fading.	None.
LL12mw-243	04/25/19	The guard posts show moderate rusting. The well paint and ID are in good condition.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
LL12mw-244	04/25/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is faded.	The guard posts, well casing, and well ID were painted in October 2019.
LL12mw-245	04/25/19	The guard posts show moderate rusting. The well paint and ID are in good condition.	None.
LL12mw-246	04/25/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.
LL12mw-247	04/25/19	The guard posts are in good condition. The well paint is showing moderate rust, and the ID is not visible.	The guard posts, well casing, and well ID were painted in October 2019.
LNWmw-024	04/23/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is beginning to fade.	None.
LNWmw-025	04/23/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is beginning to fade.	None.
LNWmw-026	04/23/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is beginning to fade.	None.
LNWmw-027	04/23/19	The guard posts show moderate rusting, but the well paint is in good condition. The ID is beginning to fade.	None.
MBS-001	04/24/19	The guard posts and well paint are in good condition. The ID is faded.	The well ID was repainted in October 2019.
MBS-002	04/24/19	The guard posts and well paint are in good condition. The ID is faded.	The well ID was repainted in October 2019.
MBS-003	04/24/19	The guard posts and well paint are in good condition. The ID is faded.	The well ID was repainted in October 2019.
MBS-004	04/24/19	The guard posts and well paint are in good condition. The ID is faded. The well pad is raised due to frost heaving.	The well ID was repainted in October 2019.
MBS-005	04/24/19	The guard posts and well paint show moderate rusting. The ID is faded and not visible.	The well ID was repainted in October 2019.
MBS-006	04/24/19	The guard posts and well paint show moderate rusting. The ID is faded and not visible.	None.
NTAmw-107	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.
NTAmw-108	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.
NTAmw-109	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
NTAmw-110	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.
NTAmw-111	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.
NTAmw-112	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading. One post is leaning over.	None.
NTAmw-113	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.
NTAmw-114	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.
NTAmw-115	04/24/19	The guard posts show moderate rusting. The well paint and ID are in good condition.	None.
NTAmw-116	04/24/19	The guard posts show moderate rusting. The well paint and ID are in good condition.	None.
NTAmw-117	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is faded.	None.
NTAmw-118	04/24/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.
NTAmw-119	04/24/19	The guard posts are in good condition. The well paint is moderately rusted/chipped, and the ID is not visible. The well pad is cracked.	None.
NTAmw-120	04/24/19	The well is in good condition; the ID needs to be painted on.	The well ID was repainted in October 2019.
RQLmw-006	04/29/19	The guard posts are in good condition. The well paint is showing minor rust, and the ID is faded.	None.
RQLmw-007	04/29/19	No guard posts. The well paint is showing minor rust, and the ID is fading.	None.
RQLmw-008	04/29/19	No guard posts. The well paint is showing minor rust, and the ID is fading.	None.
RQLmw-009	04/29/19	No guard posts. The well paint is showing minor rust, and the ID is fading.	None.
RQLmw-010	04/29/19	The guard posts and well paint show minor rusting. The ID is in good condition.	The well ID was repainted in September 2019.
RQLmw-011	04/29/19	The guard posts and well paint show minor rusting. The ID is fading. The well pad is cracked.	The well ID was repainted in September 2019.
RQLmw-012	04/29/19	The guard posts and well paint show minor rusting. The ID is fading.	The well ID was repainted in September 2019.
RQLmw-013	04/29/19	The well is in good condition; no issues.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
RQLmw-014	04/29/19	The guard posts and well paint show very minor rusting. The ID is fading.	None.
RQLmw-015	04/29/19	The guard posts show minor rusting. The well paint and ID are in good condition.	None.
RQLmw-016	04/29/19	The guard posts show minor rusting. The well paint and ID are in good condition.	None.
RQLmw-017	04/29/19	The well is in good condition; no issues.	None.
SCFmw-001	04/25/19	The well is in good condition; no issues.	None.
SCFmw-002	04/25/19	The guard posts show minor rusting. The well paint and ID are in good condition.	The guard posts, well casing, and well ID were painted in October 2019.
SCFmw-003	04/25/19	The well is in good condition; the ID needs to be painted on.	The guard posts, well casing, and well ID were painted in July 2019.
SCFmw-004	04/25/19	The guard posts and well paint show moderate to heavy rusting. The ID is no longer visible.	None.
SCFmw-005	04/29/19	The guard posts show moderate rusting. The well paint is in good condition, but the ID is fading.	None.
SCFmw-006	04/29/19	The guard posts show minor rusting. The well paint and ID are in good condition.	None.
SCLmw-001	04/23/19	The well is in good condition; the ID needs to be painted on.	None.
SCLmw-002	04/23/19	The well is in good condition; the ID needs to be painted on.	None.
SCLmw-003	04/23/19	The well is in good condition; the ID needs to be painted on.	None.
WBGmw-005	04/23/19	The guard posts and well paint show minor rusting. The ID is fading. The hinge on the well lid is broken and cannot be secured.	None.
WBGmw-006	04/23/19	The guard posts and well paint show minor rusting. The ID is fading.	The well casing was repaired in October 2019.
WBGmw-007	04/23/19	The guard posts and well paint are in good condition. The ID is faded and not visible.	None.
WBGmw-008	04/23/19	The guard posts and well paint are in good condition. The ID is faded and not visible.	None.
WBGmw-009	04/23/19	The guard posts and well paint are in good condition. The ID is fading. The hinge on the well lid is broken and cannot be secured.	None.
WBGmw-010	04/23/19	The guard posts and well paint show moderate rusting. The ID is still in good condition. The well pad is raised from frost heave.	None.
WBGmw-011	04/23/19	The guard posts and well paint are in good condition. The ID is faded and hard to read. The well pad is raised from frost heave.	None.

RVAAP Facility-Wide Monitoring Well Conditions

Well ID	Date Gauged	Repairs Recommended in April 2019	Repairs Made in 2019
WBGmw-012	04/23/19	The guard posts and well paint show minor to moderate rusting. The ID is not visible. One post is leaning over.	None.
WBGmw-013	04/23/19	The guard posts and well paint show moderate rusting. The ID is not visible.	None.
WBGmw-014	04/23/19	The guard posts show moderate rusting. The ballistic steel casing is in good condition, but the ID is faded and not visible. The well pad is raised due to frost heave.	None.
WBGmw-015	04/23/19	The guard posts show moderate rusting. The ballistic steel casing is in good condition, but the ID is faded and not visible. The well pad is raised due to frost heave.	None.
WBGmw-016	04/23/19	The guard posts and well paint show moderate to heavy rusting. The ID is no longer visible.	None.
WBGmw-017	04/23/19	The guard posts and well paint show moderate to heavy rusting. The ID is no longer visible. The well pad is raised due to frost heave.	None.
WBGmw-018	04/23/19	The well casing is painted white (incorrect color). The ID is not readable. The well pad is cracked.	None.
WBGmw-019	04/23/19	The well casing is painted white (incorrect color). The ID is not present on the well pad. The well pad is cracked.	None.
WBGmw-020	04/23/19	The well casing is painted white (incorrect color).	None.
WBGmw-021	04/23/19	The well casing is painted white (incorrect color).	None.

THIS PAGE INTENTIONALLY LEFT BLANK.