

nevenna Arrenal, Iro FWD FOR L7 Information L3 Compliance en applicable

Reply NL George V. Voinovich, Governor

Division of State Fire Marshal • Bureau of Underground Storage Tank Regulations 9221 Ravenna Road, Suite D7-D8 • Twinsburg, OH 44087 • (216) 425-9848

Nancy S. Chiles, Director

April 9, 1992

Sue McCauslin Ravenna Arsenal, Inc. 8451 State Route 5 Ravenna, OH 44266-9297 RE: Ravenna Army Ammunition Plant tank RV23 (Building 1045) 8451 State Route 5 Ravenna, OH 44266-9297 Portage County Incident #679298-11

Dear Ms. McCauslin:

The State Fire Marshal, Bureau of Underground Storage Tank Regulations, (SFM, BUSTR) has received all required information regarding corrective actions of an underground storage tank (UST) release at the aforementioned location. Upon review of the analytical results and required reports, at this time BUSTR is not requiring further corrective actions of any contamination resulting from petroleum UST activity at the facility.

Due to information potentially not discovered or revealed, nothing in this letter should be interpreted as a guarantee or warrantee that no problems exist at the aforementioned location. In addition, this letter does not release the responsible party from future responsibility and liability under sections 3737.88 through 3737.89 of the Ohio Revised Code and other state laws and regulations or under the Federal Clean Water Act, Resource Conservation and Recovery Act, or Comprehensive Environmental Response, Compensation, and Liability Act for remedying conditions resulting from any release of contaminants to the environment.

If you have any questions about this determination, you can write to us at 9221 Ravenna Road, Suite D7, Twinsburg, Ohio 44087-2443, or telephone us at (216) 425-9848.

Sincerely,

Michelle Tarka Site Coordinator

michelle Tarka

MT/sk

cc: File #679298-11
Virginia Black, Ravenna Health Department

