Ravenna Army Ammunition Plant Restoration Advisory Board Meeting Agenda

DATE: Monday, 27 January 1997

TIME: 6:00 P.M. - 8:30 P.M.

PLACE: Shearer Community Center 1355 Newton Falls Road Paris Township, OH

6:00	Call to Order, Adrian Stefanish, Community Co-Chair
6:00 - 6:10	Reading and approval of last meeting minutes, Becky Carter, RAB Secretary
6:10 - 6:30	Hand out RVAAP AOC Maps and address legal questions from last meeting, Tim Morgan, Army Co-Chair
6:30 - 7:15	Finalize RAB Policy/Charter, Adrian Stefanish, Community Co-Chair
7:15 - 8:15	Review Installation Restoration Program (IRP) Process, Bob Whelove, IOC and Eileen Mohr, OEPA - Internal Process/Action Plans/Budgeting/A106/etc DSMOA - CERCLA - RCRA - RRSE - Science Applications International Corp Documents Completed - Preliminary Assessment - Facility-Wide Sampling and Analysis Plan - Safety and Health Plan - Quality Control Plan - What documents does the RAB want the Army to provide?
8:15 - 8:30	Schedule Next Meeting
8:30	Meeting Adjourned, Adrian Stefanish, Community Co-Chair

List of Acronyms

RAB - Restoration Advisory Board

IOC - U.S. Army Industrial Operations Command

OEPA - Ohio Environmental Protection Agency

IRP - Installation Restoration Program

DSMOA - Department of Defense and State Memorandum of Agreement

CERCLA - Comprehensive Environmental Restoration, Compensation, and Liability Act

RCRA - Resource Conservation and Recovery Act RRSE - Relative Risk Site Evaluation