

Active Thermal Concepts

Cedar Rapids, IA Phone: 393-8088 Fax: 393-8081

Visual Inspection Certification

Date: 10-28-03 Job Name: Ravenna LL #6 Job Number: 030620

Description of Work Area: 2F3 sump at load line #6 is free of all asbestos material and also load lines are free of asbestos material

Contractor's Representative


The contractor's representative hereby certifies that he has visually inspected the work area and decontamination unit. All surfaces were free from debris, dust, or residue.

Visual Inspection Completed By: Charles R Burgess Date: 10-28-03

Print Name: Charles R Burgess Title: Super Viser

Building Owner or Representative

I hereby certify that I have visually inspected the work area and decontamination unit. The areas were found to have no debris, dust, or residue.

Visual Inspection Completed By:  Date: 28 Oct. 03

Print Name: Brian Stockwell Title: PM

ACTIVE THERMAL CONCEPTS

1110 INDUSTRIAL AVE. HIAWATHA, IA 52233

PHONE: 319-393-8088 1-800-495-6202 FAX: 319-3938081

JOB NAME #REF! U-6
JOB NUMBER 30326 030612 ?
DATE 8/25

2F-1

VISUAL INSPECTION

Description of the work area and materials that were removed: LEAD FLOOR
WITH TWO LAYERS OF ACM UNDER NEATH THE
LEAD FLOOR IS ALL CLEANED ALSO THE LEAD IS
FREE FROM ACM AS WELL THE CONCRETE PAD IS
CLEAN AS WELL FROM ACM

ACTIVE THERMAL'S REPRESENTATIVE

I, Chuck Bonin, hereby certify that I have completed a visual inspection of this work area including the decon and bag load area and that all areas are free from debris, dust, or residue.

Chuck Bonin
Print Name

Chuck Bonin
Signature

8/25/03
Date

BUILDING OWNER OR REPRESENTATIVE

I, KAIZAD WADIA, hereby certify that I have completed a visual inspection of this work area including the decon and bag load area and that all areas are free from debris, dust, or residue.

KAIZAD WADIA
Print Name

K. D. Wadia
Signature

8/25/03
Date

Cory Albers
Lites - Ballast
Removal

Active Thermal Concepts

Cedar Rapids, IA Phone: 393-8088 Fax: 393-8081

Visual Inspection Certification

Date: 1/15/03 Job Name: Ravenna LL6 Job Number: 020921

Description of Work Area: LITES - BALLAST Removal
TOTAL BALLAST 723 - Bulbs 2116

Contractor's Representative

The contractor's representative hereby certifies that he has visually inspected ~~the work area and decontamination unit.~~ ^{all buildings at Load Line 6,} All surfaces were free from debris, dust, or residue. ^{The areas} All light bulbs and ballasts have been removed.

Visual Inspection Completed By: Chuck Bona Date: 1/15/03

Print Name: Chuck Bona Title: FOREMAN

Building Owner or Representative

I hereby certify that I have visually inspected ^{buildings at Load Line 6.} the ~~work area and decontamination unit.~~ ^{The areas} were found to have no debris, dust, or residue. ^{to have no light bulbs or ballasts.}

Visual Inspection Completed By: James E. Panozzo Date: 1/15/03

Print Name: James E. Panozzo Title: Environmental Scientist / Asbestos Inspector / Management Planner

COREY ALLOES
LITES-BALLAST
Removal

Active Thermal Concepts

219

Cedar Rapids, IA Phone: 393-8088 Fax: 393-8081

Visual Inspection Certification

Date: 1/15/03 Job Name: Ravenna LL9 Job Number: 020922

Description of Work Area: BUILDINGS AS LISTED DT-2-5-12-13-14
15-16-18-18A-20-21-22-23-24-27
TOTALS: Bulbs 1392- BALLAST 743

Contractor's Representative

The contractor's representative hereby certifies that he has visually inspected ~~the work area and decontamination unit~~. All surfaces were free from debris, dust, or residue. *all buildings @ Lead Line 9. All light bulbs and ballasts have been removed.*

Visual Inspection Completed By: *Chueh Bawia* Date: 1/15/03
Print Name: Chueh Bawia Title: Foreman

Building Owner or Representative

I hereby certify that I have visually inspected ~~the work area and decontamination unit~~. *buildings at Lead Line 9. The areas* were found to have no debris, dust, or residue. *The buildings were found to have no light bulbs or ballasts.*

Visual Inspection Completed By: *James E. Panozzo* Date: 1/15/03
Print Name: James E. Panozzo Title: Environmental Scientist
Asbestos Inspector /
Management Planner

LL-6
Cory Alber's
N/A

Active Thermal Concepts

Cedar Rapids, IA Phone: 393-8088 Fax: 393-8081

Visual Inspection Certification

Date: 1-15-03 Job Name: Ravenna LL6 Job Number: 020921

Description of Work Area: Total Asbestos Removed at
LL-6 131,774

Contractor's Representative

The contractor's representative hereby certifies that he has visually inspected the work area and decontamination unit. All surfaces were free from debris, dust, or residue.

Visual Inspection Completed By: Chuck Bown Date: 1/15/02
Print Name: Chuck Bown Title: Foreman

Building Owner or Representative

I hereby certify that I have visually inspected the work area and decontamination unit. The areas were found to have no debris, dust, or residue.

Visual Inspection Completed By: James Panozzo Date: 1/15/03
Print Name: James Panozzo Title: Environ. Scientist
Asbestos Inspector /
Management Planner

ACTIVE THERMAL CONCEPTS

1110 INDUSTRIAL AVE. HIAWATHA, IA 52233

PHONE: 319-393-8088 1-800-495-6202 FAX: 319-3938081

JOB NAME Rayanna AR Senal IAC
JOB NUMBER 03/006
DATE 10-17-03

VISUAL INSPECTION

Description of the work area and materials that were removed: All visible lead debris has been visual cleared on 6-9 Habs
LL 6+9 Lead Floor Liners

ACTIVE THERMAL'S REPRESENTATIVE

I, Charles R Burgess, hereby certify that I have completed a visual inspection of this work area including the decon and bag load area and that all areas are free from debris, dust, or residue.

Charles R Burgess
Print Name

Charles R Burgess
Signature

10-17-03
Date

BUILDING OWNER OR REPRESENTATIVE

I, Brian Stockwell, hereby certify that I have completed a visual inspection of this work area including the decon and bag load area and that all areas are free from debris, dust, or residue.

Brian Stockwell
Print Name

B.A. Stockwell
Signature

10-17-03
Date

Active Thermal Concepts

Cedar Rapids, IA Phone: 393-8088 Fax: 393-8081

Visual Inspection Certification

Date: 10-28-03 Job Name: Ravenna LL #9 Job Number: 030620

Description of Work Area: All pumps at load line #9, (DT-1, DT-2, DT-5, DT-11) are free of asbestos material additionally all lead lines are free of asbestos material

Contractor's Representative

The contractor's representative hereby certifies that he has visually inspected the work area and decontamination unit. All surfaces were free from debris, dust, or residue.

Visual Inspection Completed By: Charles R Burgess Date: 10-28-03

Print Name: Charles R Burgess Title: Supervisor

Building Owner or Representative

I hereby certify that I have visually inspected the work area and decontamination unit. The areas were found to have no debris, dust, or residue.

Visual Inspection Completed By: B. Stodwell Date: 29 Oct 03

Print Name: Brian Stodwell Title: PM



ACTIVE THERMAL CONCEPTS

1110 INDUSTRIAL AVE. HIAWATHA, IA 52233
PHONE: 319-393-8088 1-800-495-6202 FAX: 319-3938081

JOB NAME #REN 11-9
JOB NUMBER 0 30620
DATE 10/29/03

VISUAL INSPECTION

Description of the work area and materials that were removed: All cement slabs
area free of asbestos containing debris on load tie?
Bldgs: DT-1 through DT-12 + DT-17 + DT-25

ACTIVE THERMAL'S REPRESENTATIVE

I, Charles R. Burgess, hereby certify that I have completed a visual inspection of this work area including the decon and bag load area and that all areas are free from debris, dust, or residue.

Charles R. Burgess
Print Name

Charles R. Burgess
Signature

10/9/03
Date

BUILDING OWNER OR REPRESENTATIVE

I, Brian Stockwell, hereby certify that I have completed a visual inspection of this work area including the decon and bag load area and that all areas are free from debris, dust, or residue.

Brian Stockwell
Print Name

Brian Stockwell
Signature

10/9/03
Date

Active Thermal Concepts

Cedar Rapids, IA Phone: 393-8088 Fax: 393-8081


Visual Inspection Certification

Date: 31 March 03 Job Name: Ravenna LL9 Job Number: 020922

Description of Work Area: All walk ways @ LL9

Contractor's Representative

The contractor's representative hereby certifies that he has visually inspected the work area and decontamination unit. All surfaces were free from debris, dust, or residue. (including lead washers)

Visual Inspection Completed By:  Date: 3/31/03
Print Name: Charles Bowler Title: Foreman

Building Owner or Representative

I hereby certify that I have visually inspected the work area and decontamination unit. The areas were found to have no debris, dust, or residue.

Visual Inspection Completed By: Brian Stockwell Date: 31 March 03
Print Name: Brian Stockwell Title: Site Manager

Active Thermal Concepts

Cedar Rapids, IA Phone: 393-8088 Fax: 393-8081


Visual Inspection Certification

Date: 31 March 03 Job Name: Ravenna LL9 Job Number: 020922

Description of Work Area: Transite Roofs; Bldgs DT-1 to DT-12, DT-14 & DT-15, DT-17 to DT-19, DT-23 to ~~DT-50~~ DT-35, DT-41 to DT-50, DT-54 to DT-57 + DT-9-51.


Contractor's Representative

The contractor's representative hereby certifies that he has visually inspected the work area and decontamination unit. All surfaces were free from debris, dust, or residue. (including lead washers)

Visual Inspection Completed By:  Date: 3/31/03
Print Name: Chuck Doherty Title: Foreman

Building Owner or Representative

I hereby certify that I have visually inspected the work area and decontamination unit. The areas were found to have no debris, dust, or residue.

Visual Inspection Completed By:  Date: 31 March 03
Print Name: Brian Stockwell Title: Site Manager

Active Thermal Concepts

Cedar Rapids, IA Phone: 393-8088 Fax: 393-8081

Visual Inspection Certification

Date: 4/11/03 Job Name: Ravenna LL9 Job Number: 020922

Description of Work Area: Rolled roof material @ buildings:
DT-13, DT-16, DT-20, DT-21, DT-22 + DT-52

Contractor's Representative

The contractor's representative hereby certifies that he has visually inspected the work area and decontamination unit. All surfaces were free from debris, dust, or residue.

Visual Inspection Completed By: Chuck Bonia Date: 4/11/03
Print Name: Chuck Bonia Title: ROBERT

Building Owner or Representative

I hereby certify that I have visually inspected the work area and decontamination unit. The areas were found to have no debris, dust, or residue.

Visual Inspection Completed By: Brian Stedell Date: 4/11/03
Print Name: Brian Stedell Title: Site Manager



Diamond Environmental

P.O. Box 2543 • Stow, Ohio 44224 • (330) 686-5996

December 26, 2002

Mr. Brian Stockwell
MKM Engineers, Inc.
Ravenna Army Ammunition Plant
8451 State Route 5
Ravenna, Ohio 44266

**RE: Asbestos Inspectiojn for Asbestos Siding
Load Line 6
Diamond #2-0613**

Description of Work

Diamond Environmental, LLC. was contracted to perform a visual inspection of buildings and areas within a 10 foot area surrounding the buildings in Load Line 6 for asbestos containing transite debris in conjunction with their planned demolition by incineration at the Ravenna Army Ammunition Plant in Ravenna, Ohio. The inspection was performed by Mr. Keith Bickel, CAHES of Diamond Environmental on December 20, 2002.

The following buildings in Load Line 6 were inspected for transite debris in their interiors and within 10 feet of the exterior walls. Buildings: 6-51, 2F-32, 2F-33, 2F-34, 2F-35, 2F-12, 2F-10, 2F-11, 2F-15, 2F-20, 2F-9, 2F-18, 2F-19, 2F-1, 2F-2, 2F-3, 2F-4, 2F-31, 2F-6, 2F-7, 2F-8, 2F-13, 2F-14, and 2F-36.

No visible debris was discernible in these buildings or the surrounding 10 foot areas. The inspection was performed by Mr. Keith Bickel of Diamond Environmental (Certified Hazard Evaluation Specialist # 31476, exp. 6-12-03).

Please contact the undersigned if you require any additional information. Thank you for consulting Diamond Environmental.

Sincerely,

Diamond Environmental, LLC.

A handwritten signature in cursive script that reads "Keith R Bickel".

Keith R. Bickel, CHMM, REP, CAHES
Asbestos Project Coordinator



Diamond Environmental

P.O. Box 2543 • Stow, Ohio 44224 • (330) 686-5996

April 25, 2003

Brian Stockwell
MKM Engineers, Inc.
Ravenna Army Ammunition Plant
8451 State Route 5
Ravenna, Ohio 44266

**Re: Inspection Load Line 9
Diamond #: 3-0084**

Dear Mr. Stockwell:

Description of Work

Diamond Environmental, LLC. was contracted to perform a visual inspection for asbestos containing transite that was utilized on roofs and wall siding on Buildings and Walkways in Load Line 9 of the Ravenna Army Ammunition Plant in Ravenna, Ohio. Mr. Keith Bickel, CAHES of Diamond Environmental conducted the visual examination of the interior and exterior 10 foot radius of the buildings and walkways on April 24, 2003. Certain interior and exterior building areas were inaccessible due to wooden pallets and lumber. No transite material was observed during the visual examination.

The following buildings were completed:

- 9-51 DT-52 DT-28 DT-29 DT-22 DT-21 DT-20 DT-18A
- DT-16 DT-48 DT-13 DT-12 DT-14 DT-15 DT-17 DT-35
- DT-34 DT-1 DT-3 DT-2 DT-25 DT-4 DT-5 DT-6
- DT-7 DT-8 DT-9 DT-10 DT-11 DT-33 DT-23 DT-24
- DT-26 DT-27 and all Walkways

Please contact the undersigned if you require any additional information.

Thank you for consulting Diamond Environmental.

Sincerely,

Diamond Environmental, LLC.

Keith R. Bickel, CHMM, REP, CAHES
Asbestos Project Coordinator



SPIKER ENVIRONMENTAL inc.

November 17, 2003

Mr. Brian Stockwell
MKM Engineers, Inc.
8451 State Route 5
Ravenna, OH 44266

RE: Lead from wet storage project

Dear Mr. Stockwell:

On November 17, 2003 I, Richard A. Kuhlman (C.A.H.E.S. # 34051) performed an inspection of the lead removed from "Wet Storage". After completing the inspection it is my conclusion that no asbestos containing materials are present on the lead removed from "Wet Storage, 1, 1A, 2, and 2A".

If you have any questions concerning this matter please feel free to call my office at 330-633-0724.

Sincerely,

Richard A. Kuhlman, Vice President
Spiker Environmental, Inc.
C.A.H.E.S. #34051



SPIKER ENVIRONMENTAL inc.

November 17, 2003

Mr. Brian Stockwell
MKM Engineers, Inc.
8451 State Route 5
Ravenna, OH 44266


RE: Wet storage project

Dear Mr. Stockwell:

On November 17, 2003 I, Richard A. Kuhlman (C.A.H.E.S. # 34051) performed an asbestos inspection of the inside of "Wet Storage". After completing the inspection it is my conclusion that no friable asbestos containing materials are present in the structure called "Wet Storage, 1, 1A, 2, and 2A".

If you have any questions concerning this matter please feel free to call my office at 330-633-0724.

Sincerely,



Richard A. Kuhlman, Vice President
Spiker Environmental, Inc.
C.A.H.E.S. #34051