

APPENDIX J

Summary of Groundwater Monitoring Well Conditions and Repair Recommendations

THIS PAGE INTENTIONALLY LEFT BLANK

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
ASYmw-001	10/18/18	Guard posts need repainted.
ASYmw-002	10/18/18	Guard posts need repainted and well ID touched up.
ASYmw-003	10/18/18	Guard posts need repainted and well ID touched up.
ASYmw-004	10/18/18	Guard posts and well ID need repainted.
ASYmw-005	10/18/18	Guard posts and well ID need repainted.
ASYmw-006	10/18/18	Guard posts need repainted and well ID touched up.
ASYmw-007	10/18/18	Guard posts need repainted.
ASYmw-008	10/18/18	Guard posts and well ID need repainted.
ASYmw-009	10/18/18	Guard posts and well ID need repainted.
ASYmw-010	10/18/18	Guard posts and well ID need repainted.
B12mw-010	10/18/18	Guard posts need repainted, well ID is faded.
B12mw-011	10/18/18	Guard posts need repainted.
B12mw-012	10/18/18	Guard posts, well, and well ID need repainting.
B12mw-013	10/18/18	Good Condition - No repairs.
BKGmw-004	10/19/18	Guard posts, well, and well ID need repainting.
BKGmw-005	10/15/18	Well ID needs repainted, minor brush clearing around well.
BKGmw-006	10/22/18	Well pad cracked, minor rust on guard posts - could use repainting.
BKGmw-008	10/19/18	Rust on guard posts - could use repainting.
BKGmw-010	10/18/18	Broken hinge on well lid, guard posts, well and well ID need repainted, minor brush clearing around well.
BKGmw-012	10/17/18	Rusted hinge on well lid, minor rust could require repainting of guard posts, well and well ID, brush clearing around well.
BKGmw-013	10/17/18	Brush clearing needed on path to the well, guard posts, well and well ID need repainted.
BKGmw-015	10/22/18	Guard posts, well, and well ID need repainted, brush clearing around well required.
BKGmw-016	10/16/18	Broken hinge on well lid.
BKGmw-017	10/15/18	Guard posts, well, and well ID need repainted.
BKGmw-018	10/22/18	Guard posts and well ID need repainted.
BKGmw-019	10/17/18	Broken hinge on well lid, guard posts, well need repainted.
BKGmw-020	10/17/18	Minor rust - well repairs not required.
BKGmw-021	10/19/18	Guard posts and well ID need repainted.
BKGmw-022	10/15/18	Well ID needs painted on.
BKGmw-023	10/15/18	Well ID needs painted on.
BKGmw-024	10/22/18	Well ID needs painted on.
BKGmw-025	10/15/18	Well ID needs painted on.
CBLmw-001	10/16/18	Guard posts need repainted.

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
CBLmw-002	10/16/18	Guard posts need repainted.
CBLmw-003	10/16/18	Guard posts need repainted.
CBLmw-004	10/16/18	Guard posts need repainted.
CBLmw-005	10/16/18	Good Condition - No repairs.
CBPmw-001	10/17/18	Well and well ID need repainted, brush clearing required.
CBPmw-002	10/17/18	Well pad elevated from frost heave, brush clearing required.
CBPmw-003	10/17/18	Well and well ID need repainted.
CBPmw-004	10/17/18	Well ID needs touched up, minor paint flaking and rust on well and guard posts.
CBPmw-005	10/17/18	Well ID need repainted, minor paint chipping, brush clearing required.
CBPmw-006	10/17/18	Well ID need repainted, minor paint chipping, brush clearing required.
CBPmw-007	10/17/18	Well ID need repainted, minor paint chipping, brush clearing required.
CBPmw-008	10/18/18	Well ID needs touched up.
CBPmw-009	10/17/18	Guard posts and well were painted over in white (wrong color) the well ID is still in yellow.
CPmw-001	10/17/18	Good Condition - No repairs.
CPmw-002	10/18/18	Guard posts need repainted, well is flush-mount so ID will need to be added to posts.
CPmw-003	10/17/18	Guard posts need to be repainted, well is flush-mount so ID needs to be repainted, bolt holders are stripped and flush-mount lid cannot be secured.
CPmw-004	10/17/18	Guard posts, well, and well ID paint needs touched up.
CPmw-005	10/17/18	Guard posts, well, and well ID need repainted.
CPmw-006	10/17/18	Guard posts, well, and well ID need repainted.
DA2mw-104	10/17/18	Well ID needs repainted, minor brush clearing around well.
DA2mw-105	10/17/18	Well ID needs repainted, minor brush clearing around well.
DA2mw-106	10/17/18	Needs bush clearing and repainted.
DA2mw-107	10/17/18	Guard posts need repainted.
DA2mw-108	10/17/18	Flaking paint and rust on well, Well ID needs repainted.
DA2mw-109	10/17/18	Minor paint flaking, needs brush clearing.
DA2mw-110	10/17/18	Minor paint flaking and rust on guard posts. Concrete pads around post and well have raised above ground level.
DA2mw-111	10/17/18	Paint flaking and rust on well and guard posts, well ID needs repainted, well pad has been undercut by erosion.

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
DA2mw-112	10/17/18	Paint flaking and rust on well and guard posts, well ID needs repainted, brush clearing needed.
DA2mw-113	10/17/18	Paint flaking and rust on well and guard posts, well ID needs repainted, brush clearing needed.
DA2mw-114	10/17/18	Incorrect color - well and guard posts are white.
DA2mw-115	10/17/18	Incorrect color - well and guard posts are white.
DET-001B	10/17/18	Well, guard posts, and well ID need repainted. ID is incorrect. Well pad is elevated from frost heave.
DET-002	10/17/18	Guard posts need repainted. Minor flaking and rust on well.
DET-003	10/17/18	Guard posts need repainted, well ID needs repainted, minor brush clearing.
DET-004	10/17/18	Well, guard posts, and well ID need repainted. Brush clearing needed.
EBGmw-123	10/19/18	Minor paint flaking on guard posts - Brush clearing is required for future access.
EBGmw-124	10/19/18	Brush clearing is required for future access.
EBGmw-125	10/19/18	Minor paint flaking on guard posts and well, well ID needs minor touch up.
EBGmw-126	10/19/18	Minor paint flaking and rust, well ID needs repainted.
EBGmw-127	10/19/18	Good Condition - No repairs.
EBGmw-128	10/19/18	Paint flaking on guard posts.
EBGmw-129	10/19/18	Good Condition - No repairs.
EBGmw-130	10/19/18	Paint flaking on guard posts, well ID fading needs touched up.
EBGmw-131	10/19/18	Cracks in well pad.
FBQmw-166	10/15/18	Well ID needs repainted.
FBQmw-167	10/15/18	Well ID needs repainted, minor brush clearing around well.
FBQmw-168	10/15/18	Good Condition - No repairs.
FBQmw-169	10/16/18	Brush clearing is required for future access.
FBQmw-170	10/15/18	Well ID needs touched up.
FBQmw-171	10/15/18	Good Condition - No repairs.
FBQmw-172	10/15/18	Well ID needs touched up.
FBQmw-173	10/16/18	Well ID needs touched up, MAJOR Brush clearing needed.
FBQmw-174	10/15/18	Guard posts are faded.
FBQmw-175	10/15/18	Good Condition - No repairs.
FBQmw-176	10/15/18	Good Condition - No repairs.
FBQmw-177	10/15/18	Well ID needs touched up.
FWGmw-001	10/19/18	All paint is slightly faded but labeling still visible.

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
FWGmw-002	10/19/18	Paint is gray (wrong color) - will need to repaint everything including ID.
FWGmw-003	10/15/18	Very minor rust - labeling still visible
FWGmw-004	10/16/18	Good Condition - No repairs.
FWGmw-005	10/15/18	Good Condition - No repairs.
FWGmw-006	10/15/18	Good Condition - No repairs.
FWGmw-007	10/16/18	Well and well ID need repainted due to rust.
FWGmw-008	10/16/18	Very minor rust - repairs not required.
FWGmw-009	10/16/18	Rust - Guard posts, well, and well ID require repainting.
FWGmw-010	10/16/18	Well and well ID require repainted due to rust.
FWGmw-011	10/16/18	White paint (wrong color) - guards, well, and well ID require repainting.
FWGmw-012	10/16/18	White paint (wrong color) - guards, well, and well ID require repainting.
FWGmw-013	10/17/18	crack in well pad.
FWGmw-014	10/15/18	White paint (wrong color) - guards, well, and well ID require repainting.
FWGmw-015	10/16/18	Good Condition - No repairs.
FWGmw-016	10/16/18	Cracks in well pad.
FWGmw-017	10/19/18	Well ID needs to be added.
FWGmw-018	10/19/18	Well ID needs to be added.
FWGmw-019	10/15/18	Well ID needs to be added.
FWGmw-020	10/19/18	Well ID needs to be added.
FWGmw-021	10/19/18	Well ID needs to be added.
FWGmw-022	10/15/18	Well ID needs to be added.
FWGmw-023	10/15/18	Well ID needs to be added.
FWGmw-024	10/19/18	Well ID needs to be added.
LL1mw-063	10/16/18	Guard posts need repainted, well ID needs touched up.
LL1mw-064	10/16/18	Guard posts need repainted.
LL1mw-065	10/16/18	Guard posts need repainted.
LL1mw-067	10/16/18	Guard posts need repainted, well ID needs touched up.
LL1mw-078	10/17/18	Guard posts need repainted.
LL1mw-079	10/17/18	Guard posts and well casing need repainted, well ID is in good condition.
LL1mw-080	10/17/18	Guard posts need repainted.
LL1mw-081	10/17/18	Guard posts, well, and well ID need repainted.
LL1mw-082	10/16/18	Minor touch up of guard posts and well casing, well ID needs repainted.
LL1mw-083	10/16/18	Guard posts, well, and well ID need repainted.
LL1mw-084	10/16/18	Guard posts, well, and well ID need repainted.
LL1mw-085	10/16/18	Guard posts, well, and well ID need repainted.

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
LL1mw-086	10/16/18	Good Condition - No repairs.
LL1mw-087	10/16/18	Rust on well casing, if repainted well ID will need repainted too.
LL1mw-088	10/22/18	Well casing is black (wrong color), need well ID, needs brush clearing.
LL1mw-089	10/17/18	Well ID needs to be painted on.
LL1mw-271	10/19/18	Well casing is not painted, need painted and well ID added.
LL2mw-059	10/18/18	Guard posts, well, and well ID need repainted.
LL2mw-060	10/18/18	Guard posts need repainted.
LL2mw-261	10/18/18	Guard posts and well ID need repainted.
LL2mw-262	10/18/18	Guard posts need repainted.
LL2mw-263	10/18/18	Guard posts need repainted.
LL2mw-264	10/18/18	Guard posts, well, and well ID need repainted.
LL2mw-265	10/18/18	Well ID needs repainted.
LL2mw-266	10/18/18	Guard posts and well casing paint is faded.
LL2mw-267	10/18/18	Guard posts and well casing paint is faded.
LL2mw-268	10/18/18	Guard posts need repainted.
LL2mw-269	10/18/18	Good Condition - No repairs.
LL2mw-270	10/18/18	Guard posts and casing paint is faded, well ID needs repainted.
LL2mw-272	10/18/18	Well ID needs painted on.
LL3mw-232	10/19/18	Guard posts faded, well ID needs repainted.
LL3mw-233	10/19/18	Guard posts, well, and well ID need repainted.
LL3mw-234	10/19/18	Guard posts, well, and well ID need repainted.
LL3mw-235	10/19/18	Guard posts, well, and well ID need repainted.
LL3mw-236	10/19/18	Guard posts, well, and well ID need repainted, need brush clearing.
LL3mw-237	10/19/18	Guard posts, well, and well ID need repainted.
LL3mw-238	10/19/18	Guard posts, well, and well ID need repainted.
LL3mw-239	10/19/18	Guard posts, well, and well ID need repainted, need brush clearing.
LL3mw-240	10/19/18	Guard posts, well, and well ID need repainted, need brush clearing.
LL3mw-241	10/19/18	Guard posts, well, and well ID all faded need repainted.
LL3mw-242	10/19/18	Guard posts, well, and well ID all faded need repainted.
LL3mw-243	10/19/18	Good Condition - No repairs.
LL3mw-244	10/19/18	Guard posts and well are in white (wrong color), need repainted, doing so will cause need to repaint well ID

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
LL3mw-245	10/19/18	Good Condition - No repairs.
LL3mw-246	10/19/18	Well casing is unpainted, need well ID
LL4mw-193	10/17/18	Guard posts need repainted, well ID needs repainted.
LL4mw-194	10/17/18	Guard posts need repainted, well ID needs repainted.
LL4mw-195	10/16/18	Guard posts need repainted, well ID needs repainted.
LL4mw-196	10/16/18	Guard posts need repainted, well ID needs repainted.
LL4mw-197	10/16/18	Guard posts need repainted, well ID needs repainted.
LL4mw-198	10/17/18	Guard posts, well, and well ID all faded need repainted, brush clearing needed.
LL4mw-199	10/16/18	Guard post and well ID need repainted, brush clearing needed.
LL4mw-200	10/16/18	Well ID needs repainted.
LL4mw-201	10/16/18	Good Condition - No repairs.
LL5mw-001	10/15/18	Guard posts rusted and need repainted, well ID needs repainted.
LL5mw-002	10/15/18	Guard posts rusted and need repainted, well ID needs repainted.
LL5mw-003	10/15/18	Guard posts rusted and need repainted, well ID needs repainted.
LL5mw-004	10/15/18	Guard posts rusted and need repainted, well ID needs repainted.
LL5mw-005	10/15/18	Guard posts rusted and need repainted, well ID needs repainted.
LL5mw-006	10/15/18	Guard posts rusted and need repainted, well ID needs repainted.
LL6mw-001	10/15/18	Guard posts need repainted, well is flush-mount and one of the bolt holders has broken off.
LL6mw-002	10/15/18	Guard posts, well, and well ID need repainted.
LL6mw-003	10/15/18	Guard posts, well, and well ID need repainted.
LL6mw-004	10/15/18	Guard posts, well, and well ID need repainted.
LL6mw-005	10/15/18	Guard posts, well, and well ID need repainted.
LL6mw-006	10/17/18	Guard posts need repainted, well is flush-mount, path to well needs to be mowed.
LL6mw-007	10/17/18	Guard posts need repainted, well is flush-mount, path to well needs to be mowed. Bolts to secure lid are missing, likely that bolt holders are stripped.
LL6mw-008	10/15/18	Good Condition - No repairs.
LL6mw-009	10/15/18	Good Condition - No repairs.

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
LL7mw-001	10/15/18	Brush clearing is required for future access, guard posts and well ID need repainted.
LL7mw-002	10/15/18	Guard posts and well ID need repainting.
LL7mw-003	10/15/18	Guard posts and well ID need repainting.
LL7mw-004	10/15/18	Guard posts and well ID need repainting.
LL7mw-005	10/15/18	Guard posts and well ID need repainting.
LL7mw-006	10/15/18	Guard posts and well ID need repainting.
LL8mw-001	10/15/18	Guard posts need repainting.
LL8mw-002	10/15/18	Guard posts and Well ID need repainting.
LL8mw-003	10/15/18	Guard posts need repainting.
LL8mw-004	10/15/18	Guard posts need repainting.
LL8mw-005	10/15/18	Guard posts and well ID need repainting, large crack in well pad.
LL8mw-006	10/15/18	Guard posts and well ID need repainting, large crack in well pad.
LL9mw-001	10/16/18	One guard post is severely leaning, guard posts, well, and well ID need repainting.
LL9mw-002	10/16/18	Guard posts, well, and well ID need repainted.
LL9mw-003	10/17/18	Guard posts, well, and well ID need repainted, brush clearing required.
LL9mw-004	10/16/18	Guard posts, well, and well ID need repainted.
LL9mw-005	10/16/18	Guard posts, well, and well ID need repainted.
LL9mw-006	10/16/18	Guard posts, well, and well ID need repainted.
LL9mw-007	10/16/18	Flush-mount well - well ID needs painted on guard post.
LL10mw-001	10/16/18	Guard posts and well ID need repainted.
LL10mw-002	10/15/18	Guard posts and well ID need repainted.
LL10mw-003	10/15/18	Guard posts and well ID need repainted.
LL10mw-004	10/15/18	Crack in well pad, guard posts and well ID need repainted.
LL10mw-005	10/15/18	Guard posts and well ID need repainted.
LL10mw-006	10/15/18	Crack in well pad, guard posts need repainted.
LL11mw-001	10/15/18	Well ID needs repainted, minor rust on guard posts.
LL11mw-002	10/15/18	Flush-mount well - bolts missing, likely bolt-holders are stripped, guard posts need repainted and well ID.
LL11mw-003	10/15/18	Flush-mount well - minor rust on guard posts, need well ID added.
LL11mw-004	10/15/18	Flush-mount well - only one bolt securing well, others missing and bolt-holders likely stripped. Guard posts and well ID need repainted.

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
LL11mw-005	10/15/18	Flush-mount well - bolt-holders are stripped and well cannot be secured, Guard posts need repainted with well ID.
LL11mw-006	10/15/18	Flush-mout well - Guard posts need repainted with well ID.
LL11mw-007	10/15/18	Well pad is cracked, well ID needs repainted.
LL11mw-008	10/15/18	Flush-mount well - one bolt holder is stripped, guard posts are rusted - need repainted with well ID.
LL11mw-009	10/15/18	Minor rust on guard posts, well ID needs touched up.
LL11mw-010	10/15/18	Guard posts rusted and need repainted, well ID needs repainted.
LL11mw-011	10/15/18	Good Condition - No repairs.
LL11mw-012	10/15/18	Cracks in well pad.
LL12mw-088	10/18/18	Guard posts need repainting.
LL12mw-107	10/18/18	Good Condition - No repairs.
LL12mw-113	10/18/18	Good Condition - No repairs.
LL12mw-128	10/18/18	Guard posts need repaint, brush clearing needed.
LL12mw-153	10/18/18	Guard posts and well ID need repainted, brush clearing needed.
LL12mw-154	10/18/18	Brush clearing is required for future access.
LL12mw-182	10/18/18	Good Condition - No repairs.
LL12mw-182ss	10/18/18	Good Condition - No repairs.
LL12mw-183	10/18/18	Well ID faded - needs repaint.
LL12mw-184	10/18/18	Brush clearing is required for future access.
LL12mw-185	10/18/18	Good Condition - No repairs.
LL12mw-186	10/18/18	Guard posts need repainting.
LL12mw-187	10/18/18	Guard posts and well ID need repainted.
LL12mw-188	10/18/18	Minor repainting needed on guard posts.
LL12mw-189	10/18/18	Brush clearing required.
LL12mw-242	10/18/18	Guard posts and well ID need repainting.
LL12mw-243	10/18/18	Guard posts and well ID need repainting.
LL12mw-244	10/18/18	Guard posts and well ID need repainting.
LL12mw-245	10/19/18	Guard posts need repainting.
LL12mw-246	10/18/18	Guard posts need repainting.
LL12mw-247	10/18/18	Guard posts are white (wrong color), well casing and ID need repainted.
LNWmw-024	10/17/18	Guard posts need repainted, brush clearing needed.
LNWmw-025	10/17/18	Brush clearing needed on path to well, guard posts, well, and well ID need to be repainted.
LNWmw-026	10/17/18	MAJOR Brush clearing required, guard posts, well, and well ID need repainted.
LNWmw-027	10/17/18	Pathway to well needs cleared, guard posts need repainted, well ID needs touched up.
MBS-001	10/16/18	Well pad is submerged in standing water.

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
MBS-002	10/16/18	Well ID needs repainted.
MBS-003	10/16/18	Well ID needs repainted, well pad raised due to frost heave.
MBS-004	10/16/18	Well ID needs repainted, well pad raised due to frost heave.
MBS-005	10/16/18	Guard posts, well, and well ID need repainted.
MBS-006	10/16/18	Guard posts, well, and well ID need repainted.
NTAmw-107	10/15/18	Guard posts are rusted and need repainted.
NTAmw-108	10/15/18	Guard posts are rusted and need repainted.
NTAmw-109	10/15/18	Guard posts are rusted and need repainted, well ID needs repainted, Well Pad is not secure - loose from frost heave.
NTAmw-110	10/15/18	Guard posts are rusted and need repainted, well ID needs repainted.
NTAmw-111	10/15/18	Guard posts are rusted and need repainted, well ID needs repainted.
NTAmw-112	10/15/18	Guard posts are rusted and need repainted, one post is severely leaning, well ID needs repainted.
NTAmw-113	10/15/18	Guard posts are rusted and need repainted, well ID needs repainted.
NTAmw-114	10/15/18	Guard posts are rusted and need repainted, well ID needs repainted.
NTAmw-115	10/16/18	Guard posts are rusted and need repainted.
NTAmw-116	10/16/18	Guard posts are rusted and need repainted, well ID needs repainted.
NTAmw-117	10/16/18	Guard posts are rusted and need repainted, well ID needs repainted.
NTAmw-118	10/16/18	Guard posts, well, and well ID need repainting.
NTAmw-119	10/15/18	Good Condition - No repairs.
NTAmw-120	10/15/18	Need well ID painted on.
RQLmw-006	10/18/18	Paint is starting to flake off, rust on outer casing.
RQLmw-007	10/18/18	Paint is flaked off at bottom of casing, rust on bottom of casing.
RQLmw-008	10/18/18	Paint flaking off, rust on outer casing, well ID is faded and needs repainted.
RQLmw-009	10/18/18	Paint flaking off, well ID needs repainted, small cracks in well pad.
RQLmw-010	10/18/18	Minor flaking of paint, otherwise in good condition.
RQLmw-011	10/18/18	Minor flaking of paint, cracks in concrete pad.
RQLmw-012	10/18/18	Minor flaking of paint.
RQLmw-013	10/18/18	Good Condition - No repairs.
RQLmw-014	10/18/18	Minor flaking of paint, well ID needs touched up.

RVAAP Facility Wide Monitoring Well Conditions

October, 2018

Well ID	Date Gauged	Repairs Needed
RQLmw-015	10/18/18	Minor flaking of paint on guard posts - No repairs.
RQLmw-016	10/18/18	Minor flaking of paint on guard posts - No repairs.
RQLmw-017	10/18/18	Good Condition - No repairs.
SCFmw-001	10/15/18	Good Condition - No repairs.
SCFmw-002	10/18/18	Guard posts need repainting.
SCFmw-003	10/18/18	Guard posts need repainting.
SCFmw-004	10/16/18	Guard posts, well, and well ID need repainting.
SCFmw-005	10/18/18	Guard posts and well ID need repainting.
SCFmw-006	10/19/18	Minor paint flaking on guard posts.
WBGmw-005	10/17/18	Broken hinge on well, needs brush clearing.
WBGmw-006	10/17/18	Well, guard posts, and well ID need repainted.
WBGmw-007	10/17/18	Well ID needs repainted.
WBGmw-008	10/17/18	Well ID needs repainted, minor brush clearing around well.
WBGmw-009	10/17/18	Broken hinge on well, well ID needs repainted, brush clearing around well.
WBGmw-010	10/17/18	Flaking paint and rust on well and guard posts, brush clearing needed around well.
WBGmw-011	10/17/18	Well ID needs to be touched up.
WBGmw-012	10/17/18	Guard posts, well, and well ID need repainted, well pad raised do to frost heave, brush clearing needed.
WBGmw-013	10/17/18	Flaking paint and rust on well and guard posts, well ID needs repainted, brush clearing needed around well.
WBGmw-014	10/17/18	Well ID needs repainted, minor brush clearing around well.
WBGmw-015	10/17/18	Guard posts need repainted, well ID needs repainted, well pad elevated due to frost heave.
WBGmw-016	10/17/18	Guard posts, well, and well ID need repainted, brush clearing needed.
WBGmw-017	10/17/18	Guard posts, well, and well ID need repainted, brush clearing needed.
WBGmw-018	10/17/18	Brush clearing around well is needed, well color is white, and well ID is not present.
WBGmw-019	10/17/18	Brush clearing around well is needed, well color is white, and well ID is not present.
WBGmw-020	10/17/18	Brush clearing around well is needed, well color is white, and well ID is not present.
WBGmw-021	10/17/18	Well color is white, and well ID is not present.