




RVAAP Restoration Program Tour

A Snapshot of Sites on the Bus Tour

Presented by: Katie Tait, OHARNG Restoration Program Representative

September 18, 2024

RAB Tour Bus Route



Group 8 Munitions Response Site




- Group 8 Munitions Response Site
 - Group 8 was used for cold storage and material salvage operations; Area north of Building 849 was reportedly used for trash burning and staging
 - A remedial action including surface soil removal was completed in September 2024



Block D Munitions Response Site



- Block D was formerly used for the storage of finished munitions in earth-covered magazines
- An explosion occurred at Igloo 7-D-15 in March 1943
- Potential to encounter munitions from the past explosion exists and a remedial action including munitions removal is underway



Other Things Along the Route

